

TORC | TECH

Hydraulic Torque Wrenches

Pressure -Torque Conversion Chart

PRESSURE	TORQUE	PRESSURE	TORQUE
BAR	NM	BAR	NM
70	1006	390	5605
80	1150	400	5749
90	1293	410	5892
100	1437	420	6036
110	1581	430	6180
120	1725	440	6323
130	1868	450	6467
140	2012	460	6611
150	2156	470	6755
160	2299	480	6898
170	2443	490	7042
180	2587	500	7186
190	2731	510	7329
200	2874	520	7473
210	3018	530	7617
220	3162	540	7761
230	3305	550	7904
240	3449	560	8048
250	3593	570	8192
260	3737	580	8335
270	3880	590	8479
280	4024	600	8623
290	4168	610	8767
300	4311	620	8910
310	4455	630	9054
320	4599	640	9198
330	4743	650	9341
340	4886	660	9485
350	5030	670	9629
360	5174	680	9773
370	5317	690	9916
380	5461	700	10064

TW-S



TW-S100

The data in the pressure torque table represent the factory calibration verification values